

The following is a guide on how to provide useful photographs to help us resolve your issue more quickly.

When reporting an issue, providing photographs is a great way to assist us. However, some photographs are more useful than others and providing more than one picture can often be beneficial.



PIC 1 shows us the depth of the pothole, however, it doesn't give us an indication of its location on the path



Pic 2 shows us that the hole is near a Dog Waste bin, near a bend in the path,



This makes it much easier to locate the issue.

PIC3 shows us there is an issue with the latch, however, with lots of similar gates in the area it is hard to identify which gate this is.



PIC 4 shows the gate is situated on a lane next to a road with a metal PROW flag next to it.



All these features help us identify which gate you are concerned about.